

A3 – Transmission & Distribution Equipment
Preferential Subject 3 – Digitalisation of T&D Equipment

Monitor Data Management for Asset Failure Prevention

- 1. Abigail ZAFRIS* 2. Reynold CORNELL**
American Electric Power Service Corporation
United States
1. ajsutliff@aep.com 2. rpcornell1@aep.com

SUMMARY

Extensive asset monitoring can often lead to an overwhelming amount of information. This was the case when American Electric Power Service Corporation (AEP) began deploying online asset monitors with the primary goal of failure prevention. AEP deployed a standard monitoring package on over 400 Extra High Voltage (EHV) and High Voltage (HV) power transformer and oil-filled shunt reactor assets. AEP also deployed a monitoring package on dozens of EHV and HV circuit breaker assets. Establishing comprehensive monitoring packages on a multitude of assets creates a large volume of alarms, notifications, and data, with varying degrees of importance.

To prevent asset failures, an effective monitor data management plan must be implemented. Without this plan, valuable information is overlooked or delivered to personnel who lack the knowledge base to respond appropriately. Ensuring that the right data is delivered to the right personnel in the right timeframe is paramount to effectively using online asset monitoring systems.

An effective monitor data management plan includes three key components: data infrastructure, alarm ownership, and stakeholder training. These components must be designed for compatibility. The data infrastructure must support the transmission of data to the proper alarm owner and the owner must be trained to respond in a timely and knowledgeable manner. Issues can arise when the components are designed independently, without regard for future compatibility.

AEP's asset monitoring data infrastructure relies heavily on data concentrators utilizing IEC 61850 protocol, email alerts, data mapped to the SCADA System, and a PI Historian to house monitor data.

AEP's alarm ownership strategy has evolved over time as a result of continuous improvement efforts. The AEP Operations alarm management guide was revised. The response time to address an issue was reduced with clear ownership and action plans for operational alarms.

After the data infrastructure and alarm ownership are established, key stakeholders must be trained to respond appropriately to alarms. At AEP, there have been significant asset monitoring training efforts for field personnel and Operations. As a result, both teams are better prepared to respond appropriately to the alarms for which they are responsible.

With an effective monitor data management plan in place, AEP has been able to prevent a wide variety of failure types on a number of timescales. For example, two bushing failures were prevented after alarms triggered further investigation over several weeks. In addition, responses coordinated over several days prevented a potential power transformer failure due to inadequate cooling and a potential circuit breaker failure due to an SF6 leak. Finally, some failure preventions at AEP have required immediate action, such as a power transformer with abnormal pressure.

Asset monitoring is extremely valuable when the data is managed properly. By implementing a monitor data management plan and preventing transformer failures, AEP has achieved cost savings, greater reliability, and increased safety.

KEYWORDS

Condition – Monitor

Data – Management

Training

IEC 61580

Failure – Prevention

Bushing

Dissolved Gas Analysis

1 Introduction

American Electric Power Service Corporation (AEP) has invested in online asset monitoring solutions to facilitate asset failure prevention, condition-based maintenance, and condition-based renewal. AEP has deployed a standard monitoring package on over 400 Extra High Voltage (EHV) and High Voltage (HV) power transformer and oil-filled shunt reactor assets. The standard monitoring package for EHV power transformer and oil-filled shunt reactor assets includes technology to monitor dissolved gas, temperature, partial discharge, bushing health, and geomagnetically induced current. The standard monitoring package for HV power transformer assets has many similarities to the standard monitoring package for EHV assets, but it is scaled down to align with AEP's needs for a lower voltage level.

In addition, AEP has deployed a monitoring package on dozens of EHV and HV circuit breaker assets. AEP's circuit breaker monitoring installations include SF6 monitoring, trip and close trip coil integrity monitoring, operation duration monitoring, motor and compressor monitoring, heater circuit monitoring, and temperature monitoring. AEP's investment in online monitoring technology for power transformer, oil-filled shunt reactor, and circuit breaker assets has occurred over the course of the past 10 years. This investment includes retrofits and installations on new assets.

As the number of online asset monitoring installations grew, AEP discovered that establishing comprehensive monitoring packages on a multitude of assets creates a large volume of alarms, notifications, and data, with varying degrees of importance. Without a monitor data management plan, this wealth of information can be overwhelming. Further, valuable information can be overlooked or delivered to personnel who lack the knowledge base to respond appropriately.

In response to these challenges, an effective monitor data management plan had to be implemented at AEP. Ensuring that the right data is delivered to the right personnel in the right timeframe is paramount to effectively using online asset monitoring systems and preventing asset failures.

2 Monitor Data Management Plan

An effective monitor data management plan includes three key components: data infrastructure, alarm ownership, and stakeholder training. These components must be designed for compatibility. The data infrastructure must support the transmission of data to the proper alarm owner and the owner must be trained to respond in a timely and knowledgeable manner. Issues can arise when the components are designed independently, without regard for future compatibility.

AEP's asset monitoring data infrastructure has two elements: operational awareness and engineering analysis. For transformer and reactor monitoring, operational awareness and engineering analysis are both achieved with data concentrators utilizing IEC 61850. For operational awareness, IEC 61850 GOOSE Messaging is used to send alarms and key analog values to an alarm annunciator in the control house. The alarms and key analog values are then sent to the Remote Terminal Unit (RTU) and ultimately to AEP's SCADA System. Thus, all information with operational importance is available to AEP's Operations group.

For engineering analysis, IEC 61850 MMS is used to send all alarms, analog values, and status information to a PI Historian via an open platform communication interface server. As a result, all monitor data is readily available to asset monitoring personnel. Additionally, real-time email alerts from the data concentrators notify asset monitoring personnel of issues that need attention. Again, all necessary information is readily available to the proper personnel.




Figure 1: Operational Awareness and Engineering Analysis Data Paths Utilizing IEC 61850

Figure 1 summarizes AEP’s use of IEC 61850 and the PI Historian for asset monitor data. Additional details regarding AEP’s use of a PI Historian for asset monitor data are available in other published works [1, 2, 3].

Implementing the monitor data management plan was not without challenges. Initially, AEP’s Operations group was responsible for many asset monitoring alarms. Two primary opportunities for improvement were observed. First, the Operations group’s responsibilities included alarms that were not readily actionable. Second, when readily actionable alarms were received, the appropriate team and expected timeframe for action were often unknown. AEP’s culture of continuous improvement allowed this initiative to evolve and adapt over time. The Operations alarm management guide was revised. All stakeholders were included in the alarm management guide revision process to ensure buy-in and effective troubleshooting. The response time to address an issue was reduced with clear ownership and action plans for operational alarms.

Currently, the Operations alarm management guide includes four levels of response, outlined in the table below.

Table I: AEP SCADA Alarm Categories

Alarm Category	Required Response
Category 1	Alarm is critical, requiring immediate action.
Category 2	Alarm is non-critical and can be addressed the next business day.
Category 3	Alarm does not require any operator action and will be addressed by field personnel.
Category 4	Alarm does not require any operator action and will be addressed by asset monitoring personnel.

This system allows operators to focus on Category 1 and Category 2 alarms, which are more readily actionable. This minimizes confusion and ensures that operators will not miss alarms that require their response.

Even with these levels of response, AEP needed a framework for connecting the alarms to personnel with the knowledge to fully address them. Thus, each alarm is assigned to an owner. When an operator receives a Category 1 or Category 2 alarm, the operator contacts the appropriate alarm owner. These ownership assignments proved to more efficiently connect alarms with the personnel who can respond with the necessary expertise.

After the data infrastructure and alarm ownership are established, key stakeholders must be trained to respond appropriately to alarms. There have been two significant asset monitoring training efforts for stakeholders at AEP. First, a class was launched for field personnel, covering all transformer and reactor monitoring equipment. This class, developed in collaboration with training experts within AEP, includes both lecture and interactive content. As shown below in Figure 2, a full-scale monitoring equipment laboratory was installed at AEP’s training center to facilitate hands-on learning. As a result of this training effort, field personnel are better prepared to respond appropriately to the alarms for which they are responsible.



Figure 2: Monitoring Equipment Laboratory at AEP’s Training Center

In addition, AEP’s Operations Shift Engineers were trained on asset monitoring equipment. These engineers provide 24/7 technical support for the operators and must be able to assist in alarm response. Providing this group with the necessary skills and expertise to respond to monitoring alarms outside of the normal business hours has enabled effective alarm response and support at any hour of the day.

3 Asset Failure Prevention

Failure prevention for transmission-level assets is a shared goal for many companies. As discussed previously, effective failure prevention is challenging due to the volume and diversity of data. The diversity of data is driven by the multitude of possible failure modes for a given asset. For example, transformer failures can be driven by a variety of different components, such as windings, bushings, tap changers and leads. Circuit breaker failures arise from a variety of different causes, including mechanical issues, operational fatigue, main circuit electrical issues, auxiliary or control circuit electrical issues, and the SF6 gas system.

In response, AEP’s monitor data management plan accounts for both the volume and diversity of data with an approach that is robust yet nuanced. As a result, AEP has successfully prevented a variety of failure modes on different timescales.

3.1 Transformer Failure Prevention

At AEP, alarms generated by transformer bushing health monitors are not sent to the Operations group. Rather, they are sent directly to asset monitoring personnel. Based on experience at AEP, bushing health typically deteriorates slowly. As a result, bushing health alarms are not often readily actionable for operators. Additionally, connection issues between the bushing sensor and the bushing health monitor can corrupt data and create false alarms. Sending bushing health alarms to asset monitoring personnel allows for the identification of false alarms and analysis of real alarms over a number of weeks as the situation develops.

By sending bushing health alarms to asset monitoring personnel and involving AEP’s Operations group at the appropriate time, two bushing failures have already been prevented. The first case involved a 345 kV to 138 kV autotransformer, which initially alarmed on bushing temperature dependency. As shown in Figure 3, the low side bushing imbalance percentage correlated strongly with the transformer oil temperature. This correlation is a good indication of a real bushing issue. In addition to the temperature dependency alarm, the low side bushing imbalance percentage exceeded the warning and alert thresholds before the transformer was removed from service.




Figure 3: 345 kV to 138 kV Autotransformer Low Side Bushing Imbalance Percentage and Oil Temperature

This situation evolved over a series of months while asset monitoring personnel analyzed the data, collaborated with the monitor manufacturer, and requested an on-site inspection. During the on-site inspection, an infrared scan further confirmed that there was a bushing issue, as shown in Figure 4. Ultimately, asset monitoring personnel worked with AEP’s Operations group to remove the transformer from service. The X1 bushing was replaced, preventing a transformer failure. Moisture ingress is believed to be the root cause of this bushing issue.




Figure 4: 345 kV to 138 kV Autotransformer Infrared Scan Results

The second case involved a 138 kV to 69 kV autotransformer, which alarmed on bushing imbalance percentage for the low side bushings. The low side bushing imbalance percentage quickly rose to 11% and then fluctuated between 10% and 19% until the transformer was removed from service three weeks later. The low side bushing imbalance percentage during this timeframe is shown below in Figure 5.




Figure 5: 138 kV to 69 kV Autotransformer Low Side Bushing Imbalance Percentage

During this three-week timeframe, asset monitoring personnel analyzed the bushing data, collaborated with the monitor manufacturer, and requested an on-site inspection. The inspection revealed oil leaking from the X2 bushing and running down the side of the transformer, as shown below in Figure 6. An outage was taken to address the failing X2 bushing.



Figure 6: 138 kV to 69 kV Autotransformer Oil Leak [4]

In both cases, the monitor data management plan proved effective in providing the right data to the right personnel at the right time, leading to the prevention of two potential bushing failures which could have caused damage to the transformer or worse, harmed personnel inside or outside of the substation.

When compared to transformer bushing health alarms, transformer dissolved gas analysis (DGA) alarms are typically more readily actionable. At AEP, combustible gas alarms are sent to the Operations group with two levels of criticality. The lower criticality alarms are Response Category 2, to be investigated during the next business day. This approach has led to additional failure preventions.

For example, the composite gas reading for a 345 kV to 138 kV autotransformer reached the lower level of criticality, causing AEP's Operations group to receive an alarm. The Operations group contacted the appropriate field personnel who performed further investigation on site during normal business hours. Their analysis found that the transformer's cooling system was ineffective due to residue on the radiators. An outage was scheduled to clean the radiators and ensure the functionality of the cooling system. Figure 7 shows that the composite gas reading dropped significantly after the scheduled outage.




Figure 7: 345 kV to 138 kV Autotransformer Composite Gas Reading

Addressing this situation over a number of days was effective. The inadequate cooling was addressed before it led to a catastrophic event. These cases, like so many others, highlight the importance of understanding data and assigning alarms appropriately.

Finally, some transformer alarms require immediate action rather than a response over a series of weeks or days. Examples include extremely high levels of combustible dissolved gas, high levels of partial discharge observed with ultra-high frequency (UHF) monitoring, abnormal pressure, mechanical pressure relief, and oil level alarms.

To identify high levels of partial discharge, AEP developed a rule set based on UHF signatures from previous transformer failures. This rule set differentiates high levels of partial discharge that require immediate action from low levels of partial discharge that require engineering analysis [5]. When the rule set requirements are met, an alarm is immediately sent to AEP’s Operations group to coordinate further action.

Abnormal pressure alarms are also sent directly to AEP’s Operations group. In 2018, an abnormal pressure alarm for a 345 kV to 138 kV autotransformer, caused by the Buchholz relay, was sent to the Operations group. The Operations group and asset monitoring personnel quickly worked with relevant field personnel to take the transformer out of service in a matter of hours.

After the transformer was removed from service, further analysis was conducted. The online DGA monitor showed an upward trend in the concentrations of multiple gases, including acetylene. The acetylene concentration trend is shown below in Figure 8. The concentration was below the warning threshold for acetylene, but the increasing trend corroborated the abnormal pressure alarm.




Figure 8: 345 kV to 138 kV Autotransformer Acetylene Reading

Additionally, an onsite inspection revealed contamination on the top pressure ring, tertiary lead exit and shipping support beam. The contamination appeared to be caused by loose nuts and washers from the shipping support beam. The onsite findings further confirmed the issue identified by the abnormal pressure alarm and the acetylene trend. Quick action by field personnel, prompted by the alarm received by the Operations group, prevented a potentially

catastrophic failure, which could have damaged other assets at the station. The transformer was sent to the factory for repair.

3.2 Circuit Breaker Failure Prevention

At AEP, most circuit breaker alarms are classified as CB Maintenance Alarms or CB Operational Alarms. CB Maintenance Alarms are Category 2 alarms, requiring a next business day response. CB Operational Alarms are Category 1 alarms, requiring an immediate response.

AEP had a failure prevention experience on a 345 kV circuit breaker that exhibited a CB Maintenance Alarm. The CB Maintenance Alarm was triggered by low SF₆ pressure, detected by the circuit breaker monitor. An on-site inspection confirmed that there was an SF₆ leak located on the circuit breaker bushing, as shown in Figure 9.



Figure 9: Bubbling due to SF₆ Leak on 345 kV Circuit Breaker

AEP personnel addressed the SF₆ leak, preventing a possible circuit breaker failure event. Asset monitoring paired with proper alarm response ensured that this situation was addressed in a timely and appropriate manner.

4 Conclusion

Asset monitoring is extremely valuable when the data is managed properly. With an effective monitor data management plan in place, AEP has been able to respond appropriately to transformer, reactor, and circuit breaker issues to prevent numerous failures. These failure preventions result in cost savings, greater reliability, and increased safety.

Moving forward, AEP will continue to refine its monitor data management plan. AEP is focusing on automating data analysis to increase awareness. Much of this automation is facilitated by leveraging the wealth of data available in the PI Historian to establish automated data analysis within PI.

In addition, AEP is focusing on expanding monitoring efforts across various asset types and incorporating new monitoring systems into the existing monitor data management plan. AEP is piloting monitoring systems for underground transmission cables, substation thermal cameras, and station batteries. With the right data infrastructure, clear alarm ownership and

effective training, the groundwork has been established to enable the efficient integration of these systems into existing processes, providing immediate value and benefit to AEP.

BIBLIOGRAPHY

- [1] K. Philips, C. Schneider, P. Cambraia, M. Munson. “Automated Aggregation of Data for Asset Health Analysis” (CIGRE US National Committee Grid of the Future Symposium, 2013)
- [2] R. Cornell, P. Chung, J. Llavona, K. Zellers. “The Asset Health Center, Implementation of Online Monitoring and the Grid of the Future” (CIGRE Session, 2018)
- [3] R. Cornell, J. Jajack, R. Grawe. “Underground Transmission Cable Monitoring - Lessons Learned at AEP” (CIGRE US National Committee Grid of the Future Symposium, 2019)
- [4] C. Schneider, M. Tostrud. “Lessons Learned from Online Bushing Health Monitoring” (TechCon North America, 2020)
- [5] R. Cornell, K. Zellers, B. Mehraban. “Partial Discharge Monitoring: Lessons Learned and Consequential Safety Improvements at AEP” (CIGRE US National Committee Grid of the Future Symposium, 2016)